

## Features

- ✓ Large, easy-to-read dual LCD displays Humidity and Temperature
- ✓ 3%RH humidity accuracy
- ✓ Calibration available on site
- ✓ Desk or wall mount
- ✓ MAX/MIN value monitor
- ✓ Audible and visual alarms, with adjustable set points, warns if limits are exceeded



## General Specifications

<b>Measurement Range</b>	Humidity: 0%RH~100%RH Temperature: -20°C~60°C; -4°F~140°F Dew Point Temperature: -20°C~60°C; -4°F ~140°F
<b>Resolution</b>	0.1°C/0.1°F/0.1%RH
<b>Accuracy</b>	Humidity: ±3.0%RH Temperature: ±0.8°C, 1.5°F
<b>Display</b>	LCD, 2lines
<b>Measuring Interval</b>	20 sec.
<b>Battery Type</b>	1.5V AAA size battery x 4
<b>Battery Lifetime</b>	Approx. one year
<b>Operating Condition</b>	0°C to 40°C; 32°F~104°F
<b>Dimensions</b>	140(L)×105(W)×26(H)mm
<b>Weight</b>	265grams
<b>Accessories</b>	Batteries, Instruction Manual